

# NWT4000 sweep and frequency calibration steps


## Flatness calibration

**ATTENTION: If curves is not flat or the linearity from -10dB to 0 dB is too compressed, then insert two 3dB attenuation to input and output both when instrument is used and when calibrated as described below. Then the linearity from 0dB down to -70dB is very accurate. The dynamic range is of course reduced by 6dB. Alternatively a single 6dB attenuator can be used and if so then place on the output not to reduce the sensitivity when used as spectrum analyzer.**


1. Connect power,connect USB to PC,power on 30 minute.
2. Opened com assiter,select COM port  
(You may remove the Chinese characters by renaming/editing the file name)




3. Select COM port, baudrate, hex, ASCII code



4. Open COM port, input 8F 60



5. Click on Send








## Frequency calibration


1. Prepare a 1GHz frequency counter, warm-up time enough, NWT4000 electric power up for 30 minutes
2. Enter VFO mode ,output 1GHz




3. Used frequency counter test nwt4000 output frequency




4. Options:



5. Input frequency counter frequency unit is Hz, press OK, frequency calibration complete.





**Special tricks if your counter does not go to 1GHz:**

**If your counter does cover 100MHz then use a gate time of 10sec to read the frequency with at least 10Hz resolution , set the VFO to 100MHz and write down the measured frequency e.g. 99.99931MHz . Then write down the frequency as if it was 10x higher with 1 Hz resolution e.g. 999999310Hz and set the VFO to 1GHz and enter 999999310 into the DDS Clock (Hz) in the Settings/Options/ menu point. Then the frequency is calibrated to within 1kHz at 4.4GHz. When measuring the 100MHz output after calibration You may experiment with the 1 Hz settings to get closer to 100MHz. Most likely you will hit the correct frequency with less than 50Hz error**